

Appendix C PHOTOGRAPHS

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 1. View of agriculture habitat. Photograph taken facing west.



Photo Location 2. View of Stream 1. Photograph taken facing upstream, west.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 2. View of Stream 1. Photograph taken facing downstream, southeast.



Photo Location 2. View of Stream 1, typical substrates.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 3. View of Open Water 1, residential retention pond. Photograph taken facing west.



Photo Location 4. View of old field habitat and construction area. Photograph taken facing downstream, south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 5. View of second growth deciduous forest habitat (SP01). Photograph taken facing east.



Photo Location 6. View of agriculture habitat (SP02). Photograph taken facing east.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 7. View of Wetland 1 (SP04). Photograph taken facing north.



Photo Location 7. View of Wetland 1 (SP04). Photograph taken facing east.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 7. View of Wetland 1 (SP04). Photograph taken facing south.



Photo Location 7. View of Wetland 1 (SP04). Photograph taken facing west.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 8. View of second growth deciduous forest habitat (SP05). Photograph taken facing southeast.



Photo Location 9. View of agriculture and second growth deciduous forest habitat. Photograph taken facing east.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 10. View of Wetland 2 (SP08). Photograph taken facing north.



Photo Location 10. View of Wetland 2 (SP08). Photograph taken facing east.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 10. View of Wetland 2 (SP08). Photograph taken facing south.



Photo Location 10. View of Wetland 2 (SP08). Photograph taken facing west.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 11. View of Open Water 2. Photograph taken facing east.



Photo Location 12. View of Wetland 3 (SP10). Photograph taken facing north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 12. View of Wetland 3 (SP10). Photograph taken facing east.



Photo Location 12. View of Wetland 3 (SP10). Photograph taken facing south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 12. View of Wetland 3 (SP10). Photograph taken facing west.



Photo Location 13. View of Wetland 4 PEM community (SP12). Photograph taken facing north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 13. View of Wetland 4 PEM community (SP12). Photograph taken facing east.



Photo Location 13. View of Wetland 4 PEM community (SP12). Photograph taken facing south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 13. View of Wetland 4 PEM community (SP12). Photograph taken facing west.



Photo Location 14. View of Wetland 4 PFO community (SP13). Photograph taken facing north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 14. View of Wetland 4 PFO community (SP13). Photograph taken facing east.



Photo Location 14. View of Wetland 4 PFO community (SP13). Photograph taken facing south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 14. View of Wetland 4 PFO community (SP13). Photograph taken facing west.



Photo Location 15. View of second growth deciduous forest habitat (SP15). Photograph taken facing west.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 16. View of Stream 2. Photograph taken facing upstream, northeast.



Photo Location 16. View of Stream 2. Photograph taken facing downstream, southwest.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 16. View of Stream 2, typical substrates.



Photo Location 17. View of Wetland 5 (SP17). Photograph taken facing north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 17. View of Wetland 5 (SP17). Photograph taken facing east.



Photo Location 17. View of Wetland 5 (SP17). Photograph taken facing south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 17. View of Wetland 5 (SP17). Photograph taken facing west.



Photo Location 18. View of residential habitat. Photograph taken facing east.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 18. View of Open Water 3, residential retention pond. Photograph taken facing west.



Photo Location 19. View of Wetland 6 (SP18). Photograph taken facing north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 19. View of Wetland 6 (SP18). Photograph taken facing east.



Photo Location 19. View of Wetland 6 (SP18). Photograph taken facing south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 19. View of Wetland 6 (SP18). Photograph taken facing west.



Photo Location 20. View of Wetland 7 (SP20). Photograph taken facing north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 20. View of Wetland 7 (SP20). Photograph taken facing east.



Photo Location 20. View of Wetland 7 (SP20). Photograph taken facing south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 20. View of Wetland 7 (SP20). Photograph taken facing west.



Photo Location 21. View of Open Water 4, residential retention pond. Photograph taken facing southeast.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 22. View of Stream 3. Photograph taken facing upstream, east.



Photo Location 22. View of Stream 3. Photograph taken facing downstream, west.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 22. View of Stream 3, typical substrates.



Photo Location 23. View of Stream 4. Photograph taken facing upstream, north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 23. View of Stream 4. Photograph taken facing downstream, south.



Photo Location 23. View of Stream 4, typical substrates.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 24. View of pasture habitat. Photograph taken facing west.



Photo Location 25. View of Stream 5. Photograph taken facing upstream, north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 25. View of Stream 5. Photograph taken facing downstream, southeast.



Photo Location 25. View of Stream 5, typical substrates.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 26. View of scrub shrub habitat. Photograph taken facing west.



Photo Location 27. View of Stream 6. Photograph taken facing upstream, north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 27. View of Stream 6. Photograph taken facing downstream, south.



Photo Location 27. View of Stream 6, typical substates.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 28. View of Stream 7. Photograph taken facing upstream, northwest.



Photo Location 28. View Stream 7. Photograph taken facing downstream, southeast.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 28. View of Stream 7, typical substrates.



Photo Location 29. View of Wetland 8 (SP22). Photograph taken facing north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 29. View of Wetland 8 (SP22). Photograph taken facing east.



Photo Location 29. View of Wetland 8 (SP22). Photograph taken facing south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 29. View of Wetland 8 (SP22). Photograph taken facing west.



Photo Location 30. View of agriculture habitat. Photograph taken facing northeast.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 31. View of Stream 8. Photograph taken facing upstream, southeast.



Photo Location 31. View of Stream 8. Photograph taken facing northwest.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 31. View of Stream 8, typical substrates.



Photo Location 32. View of Wetland 9 (SP25). Photograph taken facing north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 32. View of Wetland 9 (SP25). Photograph taken facing east.



Photo Location 32. View of Wetland 9 (SP25). Photograph taken facing south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 32. View of Wetland 9 (SP25). Photograph taken facing downstream west.



Photo Location 33. View of Stream 9, Eversole Run. Photograph taken facing upstream, north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 33. View of Stream 9, Eversole Run. Photograph taken facing downstream, south.



Photo Location 33. View of Stream 9, Eversole Run, typical substrates.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 34. View of Stream 10. Photograph taken facing upstream, northwest.



Photo Location 34. View of Stream 10. Photograph taken facing downstream, southeast.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 34. View of Stream 10, typical substrates.



Photo Location 35. View of Wetland 10 (SP27). Photograph taken facing north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 35. View of Wetland 10 (SP27). Photograph taken facing east.



Photo Location 35. View of Wetland 10 (SP27). Photograph taken facing south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 35. View of Wetland 10 (SP27). Photograph taken facing west.



Photo Location 36. View of Wetland 11 (SP29). Photograph taken facing north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 36. View of Wetland 11 (SP29). Photograph taken facing east.



Photo Location 36. View of Wetland 11 (SP29). Photograph taken facing south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 36. View of Wetland 11 (SP29). Photograph taken facing west.



Photo Location 37. View of Stream 11. Photograph taken facing upstream, northwest.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 37. View of Stream 11. Photograph taken facing downstream, southeast.



Photo Location 37. View of Stream 11, typical substrates.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 38. View of Wetland 12 (SP31). Photograph taken facing north.



Photo Location 38. View of Wetland 12 (SP31). Photograph taken facing east.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 38. View of Wetland 12 (SP31). Photograph taken facing south.



Photo Location 38. View of Wetland 12 (SP31). Photograph taken facing west.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 39. View of agriculture habitat. Photograph taken facing northwest.



Photo Location 40. View of Wetland 13 (SP32). Photograph taken facing north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 40. View of Wetland 13 (SP32). Photograph taken facing east.



Photo Location 40. View of Wetland 13 (SP32). Photograph taken facing south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 40. View of Wetland 13 (SP32). Photograph taken facing west.



Photo Location 41. View of second growth deciduous forest habitat (SP34). Photograph taken facing west.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 42. View of Wetland 14 (SP35). Photograph taken facing north.



Photo Location 42. View of Wetland 14 (SP35). Photograph taken facing east.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 42. View of Wetland 14 (SP35). Photograph taken facing south.



Photo Location 42. View of Wetland 14 (SP35). Photograph taken facing west.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 43. View of Stream 12. Photograph taken facing upstream, north.



Photo Location 43. View of Stream 12. Photograph taken facing downstream, south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 43. View of Stream 12, typical substrates.



Photo Location 44. View of Wetland 15 (SP37). Photograph taken facing north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 44. View of Wetland 15 (SP37). Photograph taken facing east.



Photo Location 44. View of Wetland 15 (SP37). Photograph taken facing south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 44. View of Wetland 15 (SP37). Photograph taken facing west.



Photo Location 45. View of Stream 13. Photograph taken facing upstream, north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 45. View of Stream 13. Photograph taken downstream, south.



Photo Location 45. View of Stream 13, typical substrates.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 46. View of Wetland 16 (SP39). Photograph taken facing north.



Photo Location 46. View of Wetland 16 (SP39). Photograph taken facing east.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 46. View of Wetland 16 (SP39). Photograph taken facing south.



Photo Location 46. View of Wetland 16 (SP39). Photograph taken facing west.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 47. View of Wetland 17 (SP41). Photograph taken facing north.



Photo Location 47. View of Wetland 17 (SP41). Photograph taken facing east.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 47. View of Wetland 17 (SP41). Photograph taken facing south.



Photo Location 47. View of Wetland 17 (SP41). Photograph taken facing west.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 48. View of Wetland 18 (SP43). Photograph taken facing north.



Photo Location 48. View of Wetland 18 (SP43). Photograph taken facing east.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 48. View of Wetland 18 (SP43). Photograph taken facing south.



Photo Location 48. View of Wetland 18 (SP43). Photograph taken facing west.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 49. View of agriculture and road ROW habitat. Photograph taken facing west.



Photo Location 50. View of US Route 33. Photograph taken facing northeast.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 51. View of Wetland 19 (SP45). Photograph taken facing north.



Photo Location 51. View of Wetland 19 (SP45). Photograph taken facing east.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 51. View of Wetland 19 (SP45). Photograph taken facing south.



Photo Location 51. View of Wetland 19 (SP45). Photograph taken facing west.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 52. View of Wetland 20 (SP47). Photograph taken facing north.



Photo Location 52. View of Wetland 20 (SP47). Photograph taken facing east.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 52. View of Wetland 20 (SP47). Photograph taken facing south.



Photo Location 52. View of Wetland 20 (SP47). Photograph taken facing west.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 53. View of new field habitat. Photograph taken facing east.



Photo Location 54. View of Wetland 21 (SP49). Photograph taken facing north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 54. View of Wetland 21 (SP49). Photograph taken facing east.



Photo Location 54. View of Wetland 21 (SP49). Photograph taken facing south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 54. View of Wetland 21 (SP49). Photograph taken facing west.



Photo Location 55. View of Wetland 22 (SP52). Photograph taken facing north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 55. View of Wetland 22 (SP51). Photograph taken facing east.



Photo Location 55. View of Wetland 22 (SP51). Photograph taken facing south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 55. View of Wetland 22 (SP51). Photograph taken facing west.




Photo Location 56. View of Wetland 23 (SP53). Photograph taken facing north.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 56. View of Wetland 23 (SP53). Photograph taken facing east.



Photo Location 56. View of Wetland 23 (SP53). Photograph taken facing south.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 56. View of Wetland 23 (SP53). Photograph taken facing west.



Photo Location 57. View of residential habitat. Photograph taken facing east.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 58. View of Open Water 6. Photograph taken facing southeast.



Photo Location 59. View of Stream 14. Photograph taken facing upstream, northwest.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 59. View of Stream 14. Photograph taken facing downstream, southeast.




Photo Location 59. View of Stream 14, typical substrates.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 60. View of Stream 15. Photograph taken facing upstream, northeast.



Photo Location 60. View of Stream 15. Photograph taken facing downstream, southwest.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 60. View of Stream 15, typical substrates.



Photo Location 61. View of pasture habitat. Photograph taken facing east.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 62. View of Open Water 7. Photograph taken facing southeast.



Photo Location 63. View of Open Water. Photograph taken facing northeast.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 64. View of Open Water 8. Photograph taken facing northeast.



Photo Location 65. View of Stream 16. Photograph taken facing upstream, northwest.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 65. View of Stream 16. Photograph taken facing downstream, southeast.



Photo Location 65. View of Stream 16, typical substrates.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 66. View of Stream 17. Photograph taken facing upstream, east.



Photo Location 66. View of Stream 17. Photograph taken facing downstream, west.

Columbia Gas of Ohio
Northern Columbus Loop Natural Gas Pipeline Project (Phase VII) – Alternate Route
Wetland and Waterbody Delineation Report



Photo Location 66. View of Stream 17, typical substrates.



Photo Location 67. View of road right-of-way (McKittrick Road) and old field habitat. Photograph taken facing south.

This foregoing document was electronically filed with the Public Utilities

Commission of Ohio Docketing Information System on

11/12/2020 2:07:46 PM

in

Case No(s). 20-1236-GA-BTX

Summary: Application Appendix D.2, Part 7 of 7 electronically filed by Ms. Melissa L. Thompson on behalf of Columbia Gas of Ohio, Inc.